
CARE AND HANDLING DPM CONNECTIONS




Top Drive Bell ½" > Tool Joint OD




Calibrate Torquing Equipment



Thread Protectors on until connection make up




Stabbing Guide (Required for DPM-ST®, optional for DPM-DS and DPM-MT®)





Tongs on the Box tool joint should be a minimum of 2 inches from the sealing shoulder

Lower Tong dies 2" below Box Shoulder



Make up connection as per DPM Data Sheet



Dope on ALL shoulders and Threads